	(+) 18816996168
AFETY DATA SHEET	Ponciplastics.com
	lyondellbase
ifax TYC 852XHS BI	LK Gen. Variant: SDS_US_GF
ersion 1.1 Revision Da	ate 10/02/2019 Print Date 01/06/2022 SDS No.: BE5
IDENTIFICATION OF THE SL	JBSTANCE/MIXTURE AND OF THE COMPANY/UNDERTAKING
Trade name	: Hifax TYC 852XHS BLK
CAS Number:	: Mixture
Chemical name	: Compounded polyolefin
Synonyms	: Polyolefin, Compounded polymer, HX TYC 852XHS BLK
Identified uses	: Manufacture of plastic articles by injection molding, extrusion or other conversion process.
Prohibited uses	: FDA Class III medical devices; European class III medical devices; Health Canada class IV Medical Devices; Applications involving permanent implantation into the body; Life-sustaining medical applications
<u>Company Address</u> Equistar Chemicals, LP	<u>Company Telephone</u> Customer Service 888 777-0232
LyondellBasell Tower, Suite	
1221 McKinney St.	
P.O. Box 2583 Houston Texas 77252-258	0
Emergency telephone nur EQUISTAR 800-245-4532 E-mail address Responsible/issuing person	: product.safety@lyb.com
HAZARDS IDENTIFICATION	
GHS Classification	
Combustible dust	
Label elements	
Signal word	: Warning
Hazard Statements	: If small particles are generated during further processing,
	handling or by other means, may form combustible dust concentrations in air.
Other hazards	
	1 / 14

	(+) 18816996168	
SAFETY DATA SHEET	Ponciplastics.com	
SALLI DATA SHELI		lyondellbasell
Hifax TYC 852XHS BLK		Gen. Variant: SDS_US_GHS
Version 1.1 Revision Date 1	0/02/2019 Print Date 01/0	6/2022 SDS No.: BE5577
No additional information ava	ilable.	
3. COMPOSITION/INFORMATION C	ON INGREDIENTS	
Mixtures Components		
Chemical name	CAS-No.	Weight %
Proprietary blend of polyolefinic	Mixture	80.0 - 100.0 %
polymers		
Contains: Additives, stabilizers	and fillers	
4. FIRST AID MEASURES		
General advice	· Take proper precautions to	ensure your own health and safety
	before attempting rescue ar	
If inhaled	medical attention.	. If signs/symptoms continue, get
		ion of fumes that may be generated ial, move the person to fresh air.
	Obtain medical attention. Keep person warm, if neces	ssary give Cardio-Pulmonary
	Resuscitation (CPR)	
In case of skin contact	· If molten material contacts t	he skin, immediately flush with
	large amounts of water to c	ool the affected tissue and polymer. mer from skin as this will remove the
	skin.	
	Obtain immediate emergend or extensive.	cy medical attention if burn is deep
In case of eye contact	: Flush eyes thoroughly with medical attention if discomf	water for several minutes and seek ort persists.
	: In case of eye contact with	
	-	ith cool running water for at least 15
	Beyond flushing, DO NOT a	attempt to remove the material
	adherent to the eye(s). Immediately seek medical a	attention.
If swallowed	: Adverse health effects due	to ingestion are not anticipated.
	2 / 14	

	(+) 18816996168
SAFETY DATA SHEET	Ponciplastics.com
Hifax TYC 852XHS BLK	
Version 1.1 Revision Date	10/02/2019 Print Date 01/06/2022 SDS No.: BE557
Notes to physician	
Symptoms	: Inhalation of process fumes and vapors may cause soreness the nose and throat and coughing.
Hazards	: Dust contact with the eyes can lead to mechanical irritation. Molten polymer may cause thermal burns.
Treatment	: Treatment of overexposure should be directed at the control o symptoms and the clinical condition of the patient.
5. FIRE-FIGHTING MEASURES	
Suitable extinguishing media	: SMALL FIRE: Use dry chemical, CO2, or water spray.
	: LARGE FIRES: Use water spray hose nozzles from a safe location.
Unsuitable extinguishing media	: None known.
Specific hazards during fire fighting	 Keep away from heat and sources of ignition. In case of fire hazardous decomposition products may be produced such as: Carbon monoxide, carbon dioxide and unburned hydrocarbons (smoke).
Special protective equipment for fire-fighters	: Wear approved positive pressure self-contained breathing apparatus and firefighter protective clothing.
Further information	 Combustible particulate solid, will decompose under fire conditions. Calorific Value: 8000 - 11000 kcal/kg Fight fire from safe distance with hose lines or monitor nozzle: Heat from fire may melt, decompose polymer, and generate flammable vapors. Move containers from fire area if it can be done without risk. Evacuate immediately in the event of opening of storage container pressure relief devices or discoloration of container. Always stay away from tanks engulfed in fire. Do not attempt to get on top of storage containers involved in
	fire. Cool storage containers with large volumes of water even after fire is out.
	3 / 14

Hifax TYC 852XHS BLK Gen. Variant: SDS_US_G Version 1.1 Revision Date 10/02/2019 Print Date 01/06/2022 SDS No.: BEI S. ACCIDENTAL RELEASE MEASURES Personal precautions : Equip responders with proper protection. Creates dangerous slipping hazard on any hard smooth surface. Equip emergency responders with proper personal protecti equipment (PPE) Avoid generating dust. Avoid generating dust. Avoid generating dust. Avoid generating dust. Avoid generating dust. Potential combustible dust hazard. Polymer particles create slipping hazard on hard smooth surfaces. Environmental precautions : Do not flush into surface water or sanitary sewer system. Methods for containment / Methods for cleaning up : On land, sweep/shovel into suitable disposal containers or vacuum using equipment which avoids ignition risk. On water, material is insoluble; collect and contain as any solid. All recovered material should be packaged, labeled, transported and disposed of or reclaimed in conformance with ge engineering practices. Reclaim where possible. 7. Handling and storage : Material is in a pellet form. If converted to small particles during further processing, handing, or by other means, may form combustible dust concentrations in air. Avoid dust accumulation in enclosed space. Use dust collection systems designed per NFPA 654 to avoid dust accumulation. Avoid generating dust; fine dust suspended in air and in the presence of an ignition source is a potential dust explosion hazard. Static discharge (spark), or other ignition sources, in high di environments may ignite the dust and result in a dust explosion	SAFETY DATA SHEET Gen. Variant: SDS_US_G Hifax TYC 852XHS BLK Gen. Variant: SDS_US_G Version 1.1 Revision Date 10/02/2019 Print Date 01/06/2022 SDS No.: BE 6. ACCIDENTAL RELEASE MEASURES Personal precautions : Equip responders with proper protection. Creates dangerous slipping hazard on any hard smooth surface. Equip emergency responders with proper personal protect equipment (PPE) Avoid generating dust. Avoid dispersal of dust in the air (i.e., clearing dust surface with compressed air). Potential combustible dust hazard. Polymer particles create slipping hazard on hard smooth surfaces. Environmental precautions : Do not flush into surface water or sanitary sewer system. Methods for containment / Methods for cleaning up : On land, sweep/shovel into suitable disposal containers or vacuum using equipment which avoids ignition risk. On water, material is insoluble; collect and contain as any solid. All recovered material should be packaged, labeled, transported and disposed of or reclaimed in conformance with ge engineering practices. Reclaim where possible. 7. Handling and storage : Material is in a pellet form. If converted to small particles during further processing, handling, or by other means, may form combustible dust concentrations in air. Avoid dust accumulation. Avoid generating dust; fine dust suspended in air and in the presence of an ignition sources, in high d environments may ignite the dust and result in a dust explosion. Bettorstatic charge may build during conveying or handling Equipment handling polymer should be conductive and mediuting to the avoid explosion.		(+) 18816996168
Version 1.1 Revision Date 10/02/2019 Print Date 01/06/2022 SDS No.: BE ACCIDENTAL RELEASE MEASURES Personal precautions : Equip responders with proper protection. Creates dangerous slipping hazard on any hard smooth surface. Equip emergency responders with proper personal protecti equipment (PPE) Avoid generating dust. Avoid generating dust. Avoid dispersal of dust in the air (i.e., clearing dust surface with compressed air). Potential combustible dust hazard. Polymer particles create slipping hazard on hard smooth surfaces. Environmental precautions : Do not flush into surface water or sanitary sewer system. Methods for containment / Methods for cleaning up : On land, sweep/shovel into suitable disposal containers or vacuum using equipment which avoids ignition risk. On water, material is insoluble; collect and contain as any solid. All recovered material should be packaged, labeled, transported and disposed of or reclaimed in conformance with go engineering practices. Reclaim where possible. 7. Handling and storage : Material is in a pellet form. If converted to small particles during further processing, handling, or by other means, may form combustible dust concentrations in air. Avoid dust accumulation in enclosed space. Use dust collection systems designed per NFPA 654 to avoid dust accumulation. Avoid generating dust; fine dust suspended in air and in the pressence of an ignition source is a potential dust explosion hazard. Static discharge (spark), or other ignition sources, in high explosion	Version 1.1 Revision Date 10/02/2019 Print Date 01/06/2022 SDS No.: BE 3. ACCIDENTAL RELEASE MEASURES Personal precautions : Equip responders with proper protection. Creates dangerous slipping hazard on any hard smooth surface. Equip emergency responders with proper personal protect equipment (PPE) Avoid generating dust. Avoid generating dust. Avoid degreating dust. Avoid degreating dust. Potential combustible dust hazard. Polymer particles create slipping hazard on hard smooth surfaces. Environmental precautions : Do not flush into surface water or sanitary sewer system. Methods for containment / Methods for cleaning up : On land, sweep/shovel into suitable disposal containers or vacuum using equipment which avoids ignition risk. On water, material is insoluble; collect and contain as any solid. All recovered material should be packaged, labeled, transported and disposed of or reclaimed in conformance with ge engineering practices. Reclaim where possible. 7. Handling and storage : Material is in a pellet form. If converted to small particles during further processing, handling, or by other means, may form combustible dust concentrations in air. Avoid dust accumulation in enclosed space. Use dust collection systems designed per NEPA 654 to avo dust accumulation. Avoid generating dust; fine dust suspended in air and in the pressence of an inplicino source is a potential dust explosion hazard. Static discharge (spark), or other ignition sources, in high entomments may ignite the dust and result in a dust explosion. Electorstatic charge may build during conveying or handling Equipment handling polymer should be conductive and	SAFETY DATA SHEET	Ponciplastics.com
ACCIDENTAL RELEASE MEASURES Personal precautions Equip responders with proper protection. Creates dangerous slipping hazard on any hard smooth surface. Equip emergency responders with proper personal protecti equipment (PPE) Avoid generating dust. Avoid dispersal of dust in the air (i.e., clearing dust surface: with compressed air), Potential combustible dust hazard. Polymer particles create slipping hazard on hard smooth surfaces. Environmental precautions Containment / Methods for containment / Methods for cleaning up Containment / Containment / Contains the surface water or sanitary sewer system. Methods for cleaning up Contains the surface water or sanitary sewer system. Methods for cleaning up Contains the surface water or sanitary sewer system. Methods for cleaning up Contains the surface water or sanitary sewer system. Methods for cleaning up Contains the surface water or sanitary sewer system. Methods for cleaning up Contains the surface water or sanitary sewer system. Methods for cleaning up Contains the surface water or containers or vacuum using equipment which avoids ignition risk. Con water, material is insoluble; collect and containers or vacuum using equipment which avoids lignition risk. Con water, material solution the preckaged, labeled, transported and disposed of or reclaimed in conformance with go engineering practices. Reclaim where possible. Madvice on safe handling Advice on safe handling Contentations in air. Avoid dust accumulation in enclosed space. Use dust collection systems designed per NFPA 654 to avoid dust accumulation. Avoid generating dust; fine dust suspended in air and in the presence of an ignition source is a potential dust explosion hazard. Static discharge (spark), or other ignition sources, in high di environments may ignite the dust and result in a dust explosion Electrostatic charge may build during conveying or handling Equipment handling polymer should be conductive and	ACCIDENTAL RELEASE MEASURES Personal precautions Equip responders with proper protection. Creates dangerous slipping hazard on any hard smooth surface. Equip emergency responders with proper personal protect equipment (PPE) Avoid generating dust. Avoid depending dust. Avoid depending dust. Avoid dispersal of dust in the air (i.e., clearing dust surface with compressed air). Potential combustible dust hazard. Polymer particles create slipping hazard on hard smooth surfaces. Environmental precautions Environmental precautions On flush into surface water or sanitary sewer system. Methods for containment / Methods for cleaning up Methods for cleaning up Methods for cleaning up Methods for cleaning up Methods for safe handling Advice on safe handling Methods for safe handling Methods for safe handling Methods for safe handling Advice on safe handling Methods for safe handling Advice on		
Personal precautions : Equip responders with proper protection. Creates dangerous slipping hazard on any hard smooth surface. Equip emergency responders with proper personal protecti equipment (PPE) Avoid generating dust. Avoid dispersal of dust in the air (i.e., clearing dust surfaces with compressed air). Potential combustible dust hazard. Polymer particles create slipping hazard on hard smooth surfaces. Environmental precautions : On land, sweep/shovel into suitable disposal containers or vacuum using equipment which avoids ignition risk. On water, material is insoluble; collect and contain as any solid. All recovered material should be packaged, labeled, transported and disposed of or reclaimed in conformance with go engineering practices. Reclaim where possible. Precautions for safe handling : Material is in a pellet form. If converted to small particles during further processing, handling, or by other means, may form combustible dust concentrations in air. Avoid dust accumulation in enclosed space. Use dust collection systems designed per NFPA 654 to avoid dust accumulation. Avoid generating dust; fine dust suspended in air and in the presence of an ignition source is a potential dust explosion hazard. Static discharge (spark), or other ignition sources, in high di environments may ignite the dust and result in a dust explosion Equipment handling polymer should be conductive and	Personal precautions : Equip responders with proper protection. Creates dangerous slipping hazard on any hard smooth surface. Equip emergency responders with proper personal protecti equipment (PPE) Avoid generating dust. Avoid generating dust Avoid dispersal of dust in the air (i.e., clearing dust surface with compressed air). Potential combustible dust hazard. Polymer particles create slipping hazard on hard smooth surfaces. Environmental precautions : On land, sweep/shovel into suitable disposal containers or vacuum using equipment which avoids ignition risk. On water, material is insoluble; collect and contain as any solid. All recovered material should be packaged, labeled, transported and disposed of or reclaimed in conformance with ge engineering practices. Reclaim where possible. 7. Handling and storage : Material is in a pellet form. If converted to small particles during further processing, handling, or by other means, may form combustible dust concentrations in air. Avoid dust accumulation in enclosed space. Use dust collection systems designed per NFPA 654 to avoid dust accumulation. Avoid generating dust; fine dust suspended in air and in the presence of an ignition source is a potential dust explosion hazard. Static discharge (spark), or other ignition sources, in high d environments may ignite the dust and result in a dust explosion Equipment handling polymer should be conductive and	Version 1.1 Revision Date	10/02/2019 Print Date 01/06/2022 SDS No.: BESS
Personal precautions : Equip responders with proper protection. Creates dangerous slipping hazard on any hard smooth surface. Equip emergency responders with proper personal protecti equipment (PPE) Avoid generating dust. Avoid dispersal of dust in the air (i.e., clearing dust surfaces with compressed air). Potential combustible dust hazard. Polymer particles create slipping hazard on hard smooth surfaces. Environmental precautions : Do not flush into surface water or sanitary sewer system. Methods for containment / Methods for cleaning up : On land, sweep/shovel into suitable disposal containers or vacuum using equipment which avoids ignition risk. On water, material is insoluble; collect and contain as any solid. All recovered material should be packaged, labeled, transported and disposed of or reclaimed in conformance with go engineering practices. Reclaim where possible. Handling and storage : Material is in a pellet form. If converted to small particles during further processing, handling, or by other means, may form combustible dust concentrations in air. Avoid dust accumulation in enclosed space. Use dust collection systems designed pr NFPA 654 to avoid dust accumulation. Avoid generating dust; fine dust supended in air and in the presence of an ignition source is a potential dust explosion hazard. Static discharge (spark), or other ignition sources, in high di environments may ignite the dust and result in a dust explosion Electrostatic charge may build during conveying or handling Equipment handling polymer should be conductive and	Personal precautions : Equip responders with proper protection. Creates dangerous slipping hazard on any hard smooth surface. Equip emergency responders with proper personal protect equipment (PPE) Avoid digenerating dust. Avoid dispersal of dust in the air (i.e., clearing dust surface with compressed air). Potential combustible dust hazard. Polymer particles create slipping hazard on hard smooth surfaces. Environmental precautions : On land, sweep/shovel into suitable disposal containers or vacuum using equipment which avoids ignition risk. On water, material is insoluble; collect and contain as any solid. All recovered material should be packaged, labeled, transported and disposed of or reclaimed in conformance with ge engineering practices. Reclaim where possible. Handling and storage : Material is in a pellet form. If converted to small particles during further processing, handling, or by other means, may form combustible dust concentrations in air. Avoid dust accumulation in enclosed space. Use dust collection systems designed per NFPA 654 to avoid dust accumulation. Avoid generating dust; fine dust suspended in air and in the presence of an ignition source is a potential dust explosion hazard. Static discharge (spark), or other ignition sources, in high d environments may ignite the dust and result in a dust explosion Equipment handling polymer should be conductive and		
Creates dangerous slipping hazard on any hard smooth surface. Equip emergency responders with proper personal protecti equipment (PPE) Avoid generating dust. Avoid dispersal of dust in the air (i.e., clearing dust surfaces with compressed air). Potential combustible dust hazard. Polymer particles create slipping hazard on hard smooth surfaces. Environmental precautions : Do not flush into surface water or sanitary sewer system. Methods for containment / Methods for containment / Methods for cleaning up Methods for cleaning up Methods for cleaning up Advice on safe handling Advice on safe handling Advice on safe handling Advice on safe handling Advice on safe handling Material is in a pellet form. If converted to small particles during further processing, handling, or by other means, may form combustible dust concentrations in air. Avoid dust accumulation in enclosed space. Use dust collection systems designed per NFPA 654 to avoid dust accumulation. Avoid generating dust; fine dust suspended in air and in the presence of an ignition source is a potential dust explosion hazard. Static discharge (spark), or other ignition sources, in high du environments may ignite the dust and result in a dust explosion Electrostatic charge may build during conveying or handling Equipment handling polymer should be conductive and	Creates dangerous slipping hazard on any hard smooth surface. Equip emergency responders with proper personal protecti equipment (PPE) Avoid generating dust. Avoid dispersal of dust in the air (i.e., clearing dust surface with compressed air). Potential combustible dust hazard. Polymer particles create slipping hazard on hard smooth surfaces. Environmental precautions : On land, sweep/shovel into suitable disposal containers or vacuum using equipment which avoids ignition risk. On water, material is insoluble; collect and contain as any solid. All recovered material should be packaged, labeled, transported and disposed of or reclaimed in conformance with gr engineering practices. Reclaim where possible. Handling and storage Material is in a pellet form. If converted to small particles during further processing, handling, or by other means, may form combustible dust concentrations in air. Avoid dust accumulation. Avoid dust accumulation. Avoid dust accumulation. Avoid dust accumulation. Avoid generating dust; fine dust suspended in air and in the presence of an ignition source is a potential dust explosion hazard. Static discharge (spark), or other ignition sources, in high d environments may ignite the dust and result in a dust explosion	. ACCIDENTAL RELEASE MEAS	URES
Methods for containment / Methods for cleaning up : On land, sweep/shovel into suitable disposal containers or vacuum using equipment which avoids ignition risk. On water, material is insoluble; collect and contain as any solid. All recovered material should be packaged, labeled, transported and disposed of or reclaimed in conformance with go engineering practices. Reclaim where possible. Handling and storage Precautions for safe handling Advice on safe handling Material is in a pellet form. If converted to small particles during further processing, handling, or by other means, may form combustible dust concentrations in air. Avoid dust accumulation in enclosed space. Use dust collection systems designed per NFPA 654 to avoid dust accumulation. Avoid generating dust; fine dust suspended in air and in the presence of an ignition source is a potential dust explosion hazard. Static discharge (spark), or other ignition sources, in high du environments may ignite the dust and result in a dust explosion Electrostatic charge may build during conveying or handling Equipment handling polymer should be conductive and	Methods for containment / Methods for cleaning up : On land, sweep/shovel into suitable disposal containers or vacuum using equipment which avoids ignition risk. On water, material is insoluble; collect and contain as any solid. All recovered material should be packaged, labeled, transported and disposed of or reclaimed in conformance with ge engineering practices. Reclaim where possible. Handling and storage Precautions for safe handling Advice on safe handling : Material is in a pellet form. If converted to small particles during further processing, handling, or by other means, may form combustible dust concentrations in air. Avoid dust accumulation in enclosed space. Use dust collection systems designed per NFPA 654 to avo dust accumulation. Avoid generating dust; fine dust suspended in air and in the presence of an ignition source is a potential dust explosion hazard. Static discharge (spark), or other ignition sources, in high d environments may ignite the dust and result in a dust explosion Electrostatic charge may build during conveying or handling Equipment handling polymer should be conductive and	Personal precautions	 Creates dangerous slipping hazard on any hard smooth surface. Equip emergency responders with proper personal protective equipment (PPE) Avoid generating dust. Avoid dispersal of dust in the air (i.e., clearing dust surfaces with compressed air). Potential combustible dust hazard. Polymer particles create slipping hazard on hard smooth
Methods for cleaning up vacuum using equipment which avoids ignition risk. On water, material is insoluble; collect and contain as any solid. All recovered material should be packaged, labeled, transported and disposed of or reclaimed in conformance with go engineering practices. Reclaim where possible. Handling and storage Precautions for safe handling Advice on safe handling If converted to small particles during further processing, handling, or by other means, may form combustible dust concentrations in air. Avoid dust accumulation in enclosed space. Use dust collection systems designed per NFPA 654 to avoid dust accumulation. Avoid generating dust; fine dust suspended in air and in the presence of an ignition source is a potential dust explosion hazard. Static discharge (spark), or other ignition sources, in high du environments may ignite the dust and result in a dust explosion Electrostatic charge may build during conveying or handling Equipment handling polymer should be conductive and	Methods for cleaning up vacuum using equipment which avoids ignition risk. On water, material is insoluble; collect and contain as any solid. All recovered material should be packaged, labeled, transported and disposed of or reclaimed in conformance with ge engineering practices. Reclaim where possible. Handling and storage Precautions for safe handling Advice on safe handling If converted to small particles during further processing, handling, or by other means, may form combustible dust concentrations in air. Avoid dust accumulation in enclosed space. Use dust collection systems designed per NFPA 654 to avoid dust accumulation. Avoid generating dust; fine dust suspended in air and in the presence of an ignition source is a potential dust explosion hazard. Static discharge (spark), or other ignition sources, in high d environments may ignite the dust and result in a dust explosion Electrostatic charge may build during conveying or handling Equipment handling polymer should be conductive and	Environmental precautions	: Do not flush into surface water or sanitary sewer system.
Precautions for safe handling Advice on safe handling : Material is in a pellet form. If converted to small particles during further processing, handling, or by other means, may form combustible dust concentrations in air. Avoid dust accumulation in enclosed space. Use dust collection systems designed per NFPA 654 to avoid dust accumulation. Avoid generating dust; fine dust suspended in air and in the presence of an ignition source is a potential dust explosion hazard. Static discharge (spark), or other ignition sources, in high due environments may ignite the dust and result in a dust explosion Electrostatic charge may build during conveying or handling Equipment handling polymer should be conductive and	Precautions for safe handling Advice on safe handling : Material is in a pellet form. If converted to small particles during further processing, handling, or by other means, may form combustible dust concentrations in air. Avoid dust accumulation in enclosed space. Use dust collection systems designed per NFPA 654 to avoid dust accumulation. Avoid generating dust; fine dust suspended in air and in the presence of an ignition source is a potential dust explosion hazard. Static discharge (spark), or other ignition sources, in high d environments may ignite the dust and result in a dust explosion Electrostatic charge may build during conveying or handling Equipment handling polymer should be conductive and		 vacuum using equipment which avoids ignition risk. On water, material is insoluble; collect and contain as any solid. All recovered material should be packaged, labeled, transported and disposed of or reclaimed in conformance with applicable laws and regulations and in conformance with good
 Advice on safe handling Material is in a pellet form. If converted to small particles during further processing, handling, or by other means, may form combustible dust concentrations in air. Avoid dust accumulation in enclosed space. Use dust collection systems designed per NFPA 654 to avoid dust accumulation. Avoid generating dust; fine dust suspended in air and in the presence of an ignition source is a potential dust explosion hazard. Static discharge (spark), or other ignition sources, in high du environments may ignite the dust and result in a dust explosion Electrostatic charge may build during conveying or handling Equipment handling polymer should be conductive and 	 Advice on safe handling Material is in a pellet form. If converted to small particles during further processing, handling, or by other means, may form combustible dust concentrations in air. Avoid dust accumulation in enclosed space. Use dust collection systems designed per NFPA 654 to avo dust accumulation. Avoid generating dust; fine dust suspended in air and in the presence of an ignition source is a potential dust explosion hazard. Static discharge (spark), or other ignition sources, in high d environments may ignite the dust and result in a dust explosion Electrostatic charge may build during conveying or handling Equipment handling polymer should be conductive and 	. Handling and storage	
If converted to small particles during further processing, handling, or by other means, may form combustible dust concentrations in air. Avoid dust accumulation in enclosed space. Use dust collection systems designed per NFPA 654 to avoid dust accumulation. Avoid generating dust; fine dust suspended in air and in the presence of an ignition source is a potential dust explosion hazard. Static discharge (spark), or other ignition sources, in high du environments may ignite the dust and result in a dust explosion Electrostatic charge may build during conveying or handling Equipment handling polymer should be conductive and	If converted to small particles during further processing, handling, or by other means, may form combustible dust concentrations in air. Avoid dust accumulation in enclosed space. Use dust collection systems designed per NFPA 654 to avo dust accumulation. Avoid generating dust; fine dust suspended in air and in the presence of an ignition source is a potential dust explosion hazard. Static discharge (spark), or other ignition sources, in high d environments may ignite the dust and result in a dust explosion Electrostatic charge may build during conveying or handling Equipment handling polymer should be conductive and	Precautions for safe handling	g
		Advice on safe handling	 If converted to small particles during further processing, handling, or by other means, may form combustible dust concentrations in air. Avoid dust accumulation in enclosed space. Use dust collection systems designed per NFPA 654 to avoid dust accumulation. Avoid generating dust; fine dust suspended in air and in the presence of an ignition source is a potential dust explosion hazard. Static discharge (spark), or other ignition sources, in high dus environments may ignite the dust and result in a dust explosion Electrostatic charge may build during conveying or handling.

		(+) 188	16996168		
SAFETY DATA S	HEET	Poncip1	astics.com	lvood	ellbasell
Hifax TYC 852)					: SDS_US_GHS
Version 1.1 Re	evision Date 10/	/02/2019	Print Date 07	1/06/2022	SDS No.: BE5577
		Metal cont should be All electric codes and combustib After hand water. When brin may develo section 10 Refer to N Dust Explo	grounded and l cal equipment sl l regulatory requ le dusts. lling, always wa ging the materia op may conden l. IFPA 654, Standossions from the	in the transfer of thi bonded. hould conform to app uirements for areas h sh hands thoroughly al to processing tem se in the exhaust ve dard for the Preventio Manufacturing, Proc	blicable electric handling with soap and peratures vapors entilation. See on of Fire and cessing, and
Fire-fighting class	:	0		Particulate Solids, fo s not easily ignite.	r safe handling.
		-			
Conditions for sa Requirements for s	-		dry location.	lles	
areas and containe Specific end use(and handli should be Store away oxidizing a Keep cont	ing. Process en used to avoid e y from excessiv agents. ainer closed to	practices during stora closures and adequa excessive dust accur we heat and away fro prevent contamination the build up of elec	ate ventilation nulation. m strong on.
• ••• •••		See Section	on 1.		
8. EXPOSURE CONTR Control parameters	OLS/PERSON/	AL PROTE	CTION		
Ingredients with	workplace con	trol param	eters		
Occupational Exp	osure Limits				
Components	CAS-No.	Туре	Limit Value	Basis Revision Date	Additional Information
Materials that can be formed when handling this product: Non- specified (inert or nuisance) dust		TWA	10 mg/m3 inhalable	US (ACGIH) 2005	
		F	5 / 14		
		5	/ 14		

(+) **18816996168**

Ponciplastics.com

Hifax TYC 852XHS BLK

SAFETY DATA SHEET

Revision Date 10/02/2019 Version 1.1

Print Date 01/06/2022

Gen. Variant: SDS US GHS SDS No.: BE5577

lyondellbasel 111

Materials that can	TWA	3 mg/m3	US (ACGIH)	
be formed when		respirable	2005	
handling this				
product: Non-				
specified (inert or				
nuisance) dust		45 m m/m 0		
Materials that can	TWA	15 mg/m3 total dust	US (OSHA)	
be formed when		total dust	2005	
handling this product: Non-				
specified (inert or				
nuisance) dust				
Materials that can	TWA	5 mg/m3	US (OSHA)	
be formed when		respirable	2005	
handling this				
product: Non-				
specified (inert or				
nuisance) dust				

Consult local authorities for acceptable exposure limits.

Exposure controls

Engineering measures

Follow the recommendations in NFPA 654 (as amended and adopted) for equipment used to handle this product.

Engineering controls, i.e. enclosed systems, should be used whenever feasible to maintain exposures below acceptable criteria. When such controls are not feasible, or sufficient to achieve full conformance, other engineering controls such as local exhaust ventilation should be used. Equipment and vessels handling combustible dust from this material should be designed to either prevent dust explosions (inerting) or safely vent dust explosions per NFPA 654 Ensure that dust-handling systems (such as exhaust ducts, dust collectors, vessels, and processing equipment) are designed in a manner to prevent the escape of dust into the work area (i.e., there is no leakage from the equipment).

Personal protective equipment

Respiratory protection	 Use process enclosures, local exhaust ventilation, or other engineering controls to keep airborne levels below recommended exposure limits. When workers are facing concentrations above the exposure limit they must use appropriate certified respirators. Use appropriate respiratory protection where atmosphere exceeds recommended limits. Where workers could be exposed to dust concentrations above the exposure limit they must use appropriate certified respirators.
Hand protection	: Wear gloves that provide thermal protection where there is a potential for contact with heated material.
Eye and face protection	: Dust service goggles should be worn to prevent mechanical
	6 / 14

(+) 18816996168

	(+) 18810990108
AFETY DATA SHEET	Ponciplastics.com
	I I III
lifax TYC 852XHS BLI ersion 1.1 Revision Date	
	injury or other irritation to eyes due to airborne particles which may result from handling this product.
Skin and body protection	: Wear suitable protective clothing.
Hygiene measures	 Selection of appropriate personal protective equipment should be based on an evaluation of the performance characteristics of the protective equipment relative to the task(s) to be performed, conditions present, duration of use, and the hazards and/or potential hazards that may be encountered during use. Use good personal hygiene practices. Wash hands before eating, drinking, smoking, or using toilet
	facilities. Take off contaminated clothing and wash before reuse.
	Ğ
PHYSICAL AND CHEMICAL PI	ROPERTIES
Appearance Color	: Pellets. : Black
Odor	: Slight.
Odor Threshold	: No value available.
Flash point	: No Data Available.
Lower explosion limit	: The minimum explosive concentration (MEC) for polymer du varies according to particle size distribution.
Upper explosion limit	: Not applicable.
Flammability (solid, gas)	: Polymer will burn but does not easily ignite.
Oxidizing properties	: Not considered an oxidizing agent.
Autoignition temperature	: > 300 °C
Decomposition temperature	: not determined
Melting point/range	: 50 - 170 °C
Boiling point/boiling range	: Not applicable.
Vapor pressure	: Not applicable.
Density	: >1 g/cm3
Water solubility	: Insoluble.

	(+) 18816996168
AFETY DATA SHEET	Ponciplastics.com
ifax TYC 852XHS BL ersion 1.1 Revision Date	
	5 10/02/2019 Finit Date 01/00/2022 5D5 No DL5
Partition coefficient: n-	: No Data Available.
octanol/water Viscosity, dynamic	: Not applicable.
Relative vapor density	: Not applicable.
Evaporation rate	: Not applicable.
Explosive properties	: No Data Available.
Other Information	: No additional information available.
STABILITY AND REACTIVITY	1
Reactivity	: No known reactivity hazards.
Chemical stability	: Stable under normal conditions.
Hazardous reactions	: Will not occur.
Conditions to avoid	: Avoid contact with strong oxidizers, excessive heat, sparks or open flame.
Materials to avoid	: Material may be softened by some hydrocarbons.
Hazardous decomposition	: Not expected to decompose under normal conditions.
products Thermal decomposition	: Carbon monoxide, olefinic and paraffinic compounds, trace amounts of organic acids, ketones, aldehydes and alcohols may be formed.
TOXICOLOGICAL INFORMA	ΓΙΟΝ
Acute toxicity	
Acute oral toxicity	: Not classified
Acute inhalation toxicity	: Not classified
Acute dermal toxicity	: Not classified
Skin corrosion/irritation	: Not a skin irritant.
Serious eye damage/eye irritation	: Not an eye irritant. Mechanical irritation is possible.
	8 / 14

	(+) 1881	6996168		
SAFETY DATA SHEET	Poncipla	stics.com	lyondellbase	<u>! </u>
Hifax TYC 852XHS BL Version 1.1 Revision Date		Print Date 01/06/2	Gen. Variant: SDS_US_GH 022 SDS No.: BE55	
Respiratory or skin sensitization	: Not classifie	ed		
Chronic toxicity				
Component Name Carbon Black	NTP	IARC 2B	OSHA Present	
Carcinogenicity	: Not classifie	1		
	carcinogeni This materia	ase under normal co	y IARC as possibly a thermoplastic resin with anditions of use, transportation	١,
Germ cell mutagenicity	: Not classifie	ed		
Reproductive toxicity				
Effects on fertility / Effects on or via lactation	: Not classifie	ed		
Effects on Development	: Not classifie	ed		
Target Organ Systemic Toxicant - Single exposure		nce or mixture is no ant, single exposure	t classified as specific target	
Target Organ Systemic Toxicant - Repeated exposure		nce or mixture is no ant, repeated expos	t classified as specific target ure.	
Aspiration hazard	: Not applical	ble.		
12. Ecological information				
Ecotoxicology Assessment				
Short-term (acute) aquatic hazard	: Not classifie	ed		
Long-term (chronic) aquatic hazard	: Not classifie	ed		
	9,	/ 14		

	(+) 18816996168
SAFETY DATA SHEET	Ponciplastics.com
SAFETY DATA SHEET	lyondellbasell
Hifax TYC 852XHS BLK	Gen. Variant: SDS_US_GHS
Version 1.1 Revision Date	
Persistence and degradability	
Biodegradability	: Not expected to be biodegradable.
Bioaccumulative potential	
Bioaccumulation	: This material is not expected to bioaccumulate.
Mobility in soil	
Mobility	: no data available
Other adverse effects	
Environmental fate and pathways	: This material is not volatile and insoluble in water.
Other information	
Additional ecological information	 Ecotoxicity is expected to be minimal based on the low water solubility of polymers. No data available on this product. However, birds, fish and other wildlife may eat pellets which may obstruct their intestinal tracts.
13. Disposal considerations	
Waste treatment methods	
Product	: All recovered material should be packaged, labeled, transported and disposed of or reclaimed in conformance with applicable laws and regulations and in conformance with good engineering practices. Reclaim where possible. Recycle if possible.
	: This material is classified as a Non-hazardous Material by RCRA.
14. TRANSPORT INFORMATION	
	10/11
	10 / 14

(+) 18816996168

Ponciplastics.com

Hifax TYC 852XHS BLK

SAFETY DATA SHEET

Version 1.1

Revision Date 10/02/2019

Print Date 01/06/2022

Gen. Variant: SDS_US_GHS 22 SDS No.: BE5577

....

Iyondellbase

Not regulated for transport

15. REGULATORY INFORMATION

TSCA 12b

No substances are subject to TSCA 12(b) export notification requirements.

Significant New Use Rules (SNUR)

No substances are subject to a Significant New Use Rule.

SARA 302/304

This product contains no known chemicals regulated under SARA 302/304.

SARA 311/312

Based upon available information, this material is classified as the following health and/or physical hazards according to Section 311 & 312:

Combustible dust

SARA 313

This product contains no known chemicals regulated under SARA 313.

State Reporting

This material may contain trace levels of the following chemical substance(s) regulated under California Proposition 65. However, LyondellBasell has not tested for the presence of listed chemical substances. It is the responsibility of the California business owner to develop his or her own regulatory compliance plan. Contact Product Safety for further information at product.safety@lyb.com.

Substance	CASRN	Type of Toxicity			
		Carcinogen	Developmental	Repro-Male	Repro- Female
Mercury	7439-97-6		Х		
Lead	7439-92-1	Х	Х	Х	Х
Nickel	7440-02-0	Х			
Cadmium	7440-43-9	Х	Х	Х	
Chromium	7440-47-3	Х			
Arsenic	7440-38-2	Х			

This product contains the following chemicals regulated by New Jersey's Worker and Community Right to Know Act:

14807-96-6 Talc, Magnesium Silicate

11 / 14

(+)	1881	69961	68
(\cdot)	1001	055010	00

Ponciplastics.com

Hifax TYC 852XHS BLK

SAFETY DATA SHEET

Version 1.1

Revision Date 10/02/2019

Print Date 01/06/2022

SDS No.: BE5577

Gen. Variant: SDS US GHS

1333-86-4 Carbon Black

This product contains the following chemicals regulated by Massachusetts' Right to Know Law:

14807-96-6 Talc, Magnesium Silicate

This product contains the following chemicals regulated by Pennsylvania's Right to Know Act:

14807-96-6Talc, Magnesium Silicate1333-86-4Carbon Black

Other international regulations

Global Inventory Status

The ingredients of this product are compliant with the following chemical inventory requirements or exemptions.

*Additional Explanatory Status Statements follow the table, as necessary.

Country/Region	Inventory	Status Description
Australia	AICS	Compliant
Canada	DSL	Compliant
China	IECSC	Compliant
Europe	REACH	See REACH Compliance Statement
Japan	ENCS	Compliant
Korea	KECI	Compliant
New Zealand	NZIoC	Compliant
Philippines	PICCS	Compliant
United States of America	TSCA	Compliant
Taiwan	TCSCA	Compliant

REACh status


If the product has been purchased from any company of the LyondellBasell group of companies registered in the European Union, we confirm that all substances in this preparation have been registered under REACh, in accordance with the deadlines set forth in REACh. (Regulation (EU) No. 1907/2006)

Contact product.safety@lyb.com for additional global inventory information.

16. OTHER INFORMATION

Material safety datasheet sections which have been updated:

12 / 14



	(+) 18816996168							
SAFETY DATA SHEET	Ponciplastics.com	lyondellbasell						
Hifax TYC 852XHS BLK Version 1.1 Revision Date 10	0/02/2019 Print Date 01/	Gen. Variant: SDS_US_GHS /06/2022 SDS No.: BE5577						
Version 1.1 Revision Date IC	0/02/2019 Pfint Date 01/	00/2022 SDS NO BESS/7						
End of Material Safety Data Sheet								